

## INTRODUCTION

February 2010, a magnitude 8.8 earthquake struck South Central Chile. Of the reinforced concrete structures, 50 were severely damaged, 4 of which were partially or totally collapsed. Chilean concrete design uses shear walls as the main lateral force resisting system, and they were a critical part in the failure of these buildings. However, the failure mechanism stumped engineers. One proposed theory suggested that because of commonly used T-shaped shear walls, the boundary elements of the web section were subject to both tension and compression with reversals of the ground motion. The intention of this research was to provide evidence of the effect tensioning a boundary element has on buckling failure.



Figure 1 & 2: Failure of shear walls after Chilean earthquake

- Chile uses American building codes
- A few differences exist and codes are loosely enforced
- Damage seen in shear walls without boundary elements
- Shear walls detailed according to ACI 318-08 Section 21.9.6.4 appeared to have no damage



Figure 3 & 4: Typical damage seen in shear walls after February earthquake

## SPECIMEN CONSTRUCTION




Figure 5: Design of special boundary element with tension heads




Figure 6: Cross-section of test specimen




Figure 7: Cross-section of tension head

## TEST PROGRAM



Figure 8: "Big Press" 4,000 kip capacity compression machine




Figure 9: Design of tension test with 300 kip capacity hydraulic jack

**SPECIMEN 1:** Loaded in tension and compression


**SPECIMEN 2:** Loaded in compression only

Tension:

- Loading rate controlled manual at roughly 1.5 kip/s
- Stopped at increments of 20 kips until yield where loading continued in increments of strain until 4% strain

Compression

- Loading rate at roughly 1.0 kip/s until total failure



Compressive strength tests for 6x12 concrete cylinders

Cylinder	S1	S2
1	5765	5959
2	5418	6097
3	5832	6094



Figure 10, 11, & 12: Instrumentation to measure displacements

- Spring loaded Novotechniks connected to removable brackets
- Wire potentiometers

## RESULTS


### S1 TENSION



### S1 COMPRESSION



### S2 COMPRESSION



## CONCLUSION

### S1 ANALYSIS

- Development of cracks present in the planes of transverse reinforcement due to stress concentrations and decreased clear cover
- Tension loading plateaus at a yield strength of approximately 183 kips, 20 kips larger than the anticipated yield strength of the rebar, can be attributed to strain hardening

- After pre-tensioning, all the compressive load was carried by the elongated rebar
- Buckling of the yielded rebar within the cracks caused uneven contact of the separated concrete, crushing the concrete on the right side
- Instability allowed global buckling of the cross section at 170 kips

### S2 ANALYSIS

- Virgin column placed in pure compression took loading until 600 kips
- Explosive spalling of the concrete and global buckling developed in a short amount of time
- Unable to declare the failure ductile as anticipated

A special boundary element subjected to tension prior to compression can only tolerate less than a third of the load capacity of a virgin boundary element. Although a more ductile failure was seen in the pre tensioned case, this drastic decrease in compression capacity is alarming. Continued analysis will take place with emphasis on Euler buckling and critical buckling load. With the following information, further research is needed: investigation under what conditions boundary elements are vulnerable to extreme tension, most probable strains likely to develop, and performance under multi-cycle loading.

## ACKNOWLEDGEMENTS

This research was supervised and partially funded by Pacific Earthquake Engineering Research (PEER) Center. Financial support was provided by the NEES Grand Challenge. The author would also like to thank Jack Moehle, Wael Hassan, and Ahmet Can Tanyeri for their mentorship, and the laboratory staff at the Richmond Field Station and Davis Hall for all their help. Any opinions, findings, and conclusions or recommendations expressed in this material are those of the authors and do not necessarily reflect those of the sponsors.

## REFERENCES

- ACI Committee 318, Building Code Requirements for Structural Concrete (ACI 318-08) and Commentary (ACI 318R-08), American Concrete Institute, Farmington Hills, MI, 349-356 pp.
- Chai, Y.H., and D.T. Elayer (1999). "Lateral Stability of Reinforced Concrete Columns under Axial Reversed Cyclic Tension and Compression," ACI Structural Journal, American Concrete Institute, V. 96, No. 5, pp. 780-789.
- EERI Special Earthquake Report, The Mw 8.8 Chile Earthquake of February 27, 2010, Earthquake Engineering Research Institute

## FURTHER INFORMATION

For additional information about the grand challenge project please visit:  
<http://peer.berkeley.edu/grandchallenge/>.