

OBSERVATIONS AFTER 5/12/2008 WENCHUAN EARTHQUAKE BASED ON FIELD RECONNAISSANCE FROM 7/4/2008 TO 7/7/2008

Khalid M. Mosalam, PhD, PE mosalam@ce.berkeley.edu

Professor and Vice Chair for Research and Technical Services
Dept. of Civil and Environmental Engineering

&

Nicholas Sitar, PhD, PEng sitar@ce.berkeley.edu

Professor and Director of the Earthquake Engineering Research Center

University of California, Berkeley, CA 94720-1710

Acknowledgements

Funding and logistical support were provided by:

Office of International Strategy Development, University of California Office of the President (UCOP);

Center for Information Technology Research in the Interest of Society (CITRIS), UC Berkeley;

Prof. Jian-hui Deng, Prof. Bixiong Li, Prof. Ping Guan, and Prof. Shijing Yan, Sichuan University, Chengdu, China;


Office of the President and International Office, Sichuan University, Chengdu, China



Outline

- ❑ Visited cities
- ❑ Dujiangyan and Zipingpu towns
- ❑ Yingxiu and Xuankou towns
- ❑ Hongkou town
- ❑ Hanwang town (Mianzhu city)
- ❑ Faulting and landslides
- ❑ Tunnels and retaining structures
- ❑ Materials and reconstruction
- ❑ Concluding remarks

Visited Cities





Dujiangyan & Zipingpu Towns

Outline

- Dujiangyan town
 - Good performance
 - Fair performance
 - Poor performance
- Zipingpu dam



Photo by J-H. Deng

Dujiangyan Town (Good Performance)





6 story building

Photo by K. Mosalam


Dujiangyan Town (Fair Performance)





Dujiangyan Town (Poor Performance) (1/3)



Stair Wells (Poor Performance) (2/3)



Dujiangyan Town (Poor Performance) (3/3)



Zipingpu Dam (1/7)

Photo by N. Sitar




Photo by J. Sun

Photo by N. Sitar





Photo by K. Mosalam



Arch bridge downstream

Zipingpu Dam (2/7)

Crest settlement ~ 73 cm at center



Photo by K. Mosalam




Photo by K. Mosalam

Power house



Photo by K. Mosalam

~ 13 cm settlement, right abutment



Spillway

Photo by K. Mosalam

Zipingpu Dam (3/7)


**Crack repair in progress,
expansion seals in process of
being replaced**



Photo by K. Mosalam



Photo by K. Mosalam



Zipingpu Dam (4/7)

Photo by K. Mosalam




Photo by K. Mosalam



Fault orientation



Photo by K. Mosalam



Photo by K. Mosalam

Zipingpu Dam (5/7)



Spillway gate

Photo by K. Mosalam




Photo by K. Mosalam

Minor damage to bridge parapet




Photo by K. Mosalam

Unbolted gate controllers toppled



Bolting equipment after earthquake

Photo by K. Mosalam

Zipingpu Dam (6/7)

Photo by K. Mosalam





Photo by K. Mosalam



Photo by K. Mosalam

Zipingpu Dam (7/7)





Yingxiu & Xuankou Towns

Outline

- ❑ Bridges
- ❑ Middle school

Bridges (1/4)

**Suspended steel bridge
(performed well)**





Photo by K. Mosalam



Bridges (2/4)



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam

Bridges (3/4)



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam

Bridges (4/4)

Collapsed intermediate span of a multi-span bridge over Zipingpu reservoir



Photo by K. Mosalam


Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Middle School





Hongkou Town

Outline

- ❑ Fault trace
- ❑ Steel building
- ❑ Buildings under construction and RC slabs
- ❑ RC Columns
- ❑ RC Beam-column joints
- ❑ Overall frame failure
- ❑ Hongkou bridge – faulting induced collapse
- ❑ Traditional versus modern structures

Crane 3 (Collapsed)



Fault Trace


Photos by K. Mosalam

SE side up > 2m

Crane 1

Crane 2

Crane 3 (Collapsed)



Crane 3



Crane 1
Crane 2



Crane 1 Crane 2 Crane 3





Steel Building




Good performance – within
the fault zone




Buildings under Construction and RC Slabs (1/2)



Buildings under Construction and RC Slabs (2/2)



RC Columns



RC Beam-Column Joints (1/2)

Photo by K. Mosalam




Photo by K. Mosalam



Photo by K. Mosalam


RC Beam-Column Joints (2/2)






RC Frame Failure Due to Faulting (1/2)



RC Frame Failure Due to Faulting (2/2)



Hongkou Bridge – Faulting Induced Collapse (1/3)



Hongkou Bridge – Faulting Induced Collapse (2/3)



Hongkou Bridge – Faulting Induced Collapse (3/3)



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam

Traditional versus Modern Structures (1/2)

Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam

Traditional versus Modern Structures (2/2)





Hanwang Town (Mianzhu City)

Outline

- Good performance
- Fair performance
- Poor performance (Complete/Partial collapses)
- Bridge collapse and fault trace
- Infill walls/Masonry
- RC Beam-column joints

Clock stopped working




Photo by K. Mosalam

Time of earthquake






Photo by K. Mosalam

Good Performance (1/2)



Good Performance (2/2)



Fair Performance

6 story building




Photo by K. Mosalam

Photo by K. Mosalam



8 story building

Photo by K. Mosalam



7 story building

Photo by K. Mosalam




3 story building

Poor Performance (Partial/Complete Collapse) (1/5)



Poor Performance (Partial/Complete Collapse) (2/5)



Poor Performance (Partial/Complete Collapse) (3/5)



Poor Performance (Partial/Complete Collapse) (4/5)



Poor Performance (Partial/Complete Collapse) (5/5)

Photo by K. Mosalam



Photo by K. Mosalam




6 story building



7 story building



Bridge Collapse and Fault Trace



Infill Walls (Poor Performance)



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam

Infill Walls (Good Performance)

Photo by K. Mosalam



Photo by K. Mosalam




Photo by K. Mosalam



Photo by K. Mosalam



Masonry (Poor Performance)



Masonry (Good Performance)

Photo by B. Li



Photo by B. Li



2 story confined masonry residential buildings built in 2006 performed well (Gao Yuan Village)

Photo by B. Li

Minor cracks in masonry walls



Collapse



Photo credit to B. Li

RC Beam-Column Joints (1/2)



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam




Photo by K. Mosalam

RC Beam-Column Joints (2/2)






Faulting and Landslides



Outline

- ❑ Fault features - steeply dipping reverse faults
- ❑ Rock falls and landslides
- ❑ Slope stabilization – excellent performance

Fault Features – Steeply Dipping Reverse Faults



Rock Falls and Landslides



Slope Stabilization – Excellent Performance

**Rock Bolts and Shotcrete –
Zipingpu**



Photo by N. Sitar

Zipingpu Dam – Right Abutment




Photo by N. Sitar

Road to Yingxiu



Photo by J. Sun



Tunnels and Retaining Structures

Outline

- ❑ Tunnels – minor damage along bedding plane shears
- ❑ Conventional retaining structures – minimal or no damage

Tunnels – Minor Damage along Bedding Plane Shears



Conventional Retaining Structures – Minimal or No Damage



Photo by J. Sun




Photo by N. Sitar



Photo by N. Sitar



Photo by N. Sitar



Materials and Reconstruction

Materials and Reconstruction (1/4)




Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam

Materials and Reconstruction (2/4)

Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam



Materials and Reconstruction (3/4)



Photo by K. Mosalam



Photo by K. Mosalam



Photo by K. Mosalam

Materials and Reconstruction (4/4)



Concluding Remarks

1. Material quality (reinforced concrete, masonry)
2. Deformation compatibility (stair-wells)
3. Mixed role of unreinforced masonry infill walls
4. Poor diaphragm action (concrete planks)
5. Beam-column joints
6. Better performance of tall structures
7. Poor performance of short structures
8. Mixed response of mid-rise structures
9. Poor performance of bridges with limited or no redundancy
10. Multiple reverse fault traces along the principal fault lines
11. Thousands of slope failures and rock falls
12. Excellent performance of slope stabilization measures, tunnels and retaining walls.

Thank You!



Photo by K. Mosalam