An aerial photograph showing the aftermath of a bridge collapse. The bridge deck has fallen into a deep ravine, and several cars are overturned on the remaining sections of the bridge. Debris is scattered across the road surface. In the background, there are buildings and utility poles. The scene is captured from a high angle, looking down at the damaged infrastructure.

Damage of Transportation Facility due to 2010 Chile Earthquake

April 5, 2010

Kawashima, K., Unjoh, S.,
Hoshikuma, J. and Kosa, K.

Bridge Team Dispatched by
Japan Society of Civil Engineers

AP

45 bridges located at 30 sites were investigated

Suburbs of Concepcion

- 27. App. bridge
- 28. Las Ballenas
- 29. Lirquen
- 30. Itata

Concepcion

- 19. Jan Pablo II
- 20. Llacolen
- 21. Bio Bio
- 22. La Mochita
- 23. Laraquete

Arauko

- 24. Raqui I
- 25. Raqui II
- 26. Tubul



Santiago

- 1. Mira Flores
- 2. Lo Echeveres
- 3. Americo ves PUSIO
- 4. San Martin
- 5. Emanuel Antonio

Route 5

- 6. Maipo
- 7. Hospital
- 8. Pedestrian bridge
- 9. Augustura
- 10. Graneros
- 11. Les Mercedez
- 12. Rio Claro
- 13. Rio Maule
- 14. Longavi
- 15. Copihue
- 16. Parval
- 17. Perqui Lauquen
- 18. ? (Gerbar hinge)




Types of Damage

- Damage resulted from insufficient integrity of pre-cast concrete girder bridges due to absence of diaphragms
- Lack of constraint to rotation of deck in skewed bridges
- Damage of piers and foundations in bridges built in the early days
-

Why was damage extensive in bridges built in recent years?

Pre Mid-1990s Typical Chile Bridges


Pre-tension
PC girders



Diaphragm

Cap beam


After the Mid 1990s influenced by Spanish practice



What happened in the bridges with insufficient integrity due to absence of diaphragm?

Contact of a PC girder to stopper results in failure of lower flange, shear failure of web plate, rupture of deck slabs and connection between deck slab and upper flange

Seismic force in the TR direction




Example of damage
due to lack of
diaphragms


Llacolén Bridge
Conception



From Web



What happened if side stoppers on the top of pier cap were removed in addition to removal of diaphragms?




Vertical restrainers?

- Resist Uplift?
- Insufficient to constrain offset of a bridge in the transverse direction

Example of damage
due to lack of side
stoppers and
diaphragms

Las Mercedes Bridge
Route 5



Bridges based on recent practice suffered more damage than bridges based on pre mid-1990s practice

Perqui Lauquen Bridge
Route 5

Very lucky!
About to collapse



Lack of constraint to rotation of skewed bridges

Skewed bridges tend to rotation under seismic excitation



Watanabe, G. and
Kawashima, K., Paper No.
789, 13th WCEE, 2004

Skewed bridges which lacked diaphragms and effective side stoppers suffered extensive damage

Lo Echeveres Bridge, Santiago



From Web

Mira Flores Bridge



From Web


No mechanism to prevent TR and LG offset of bridges

Mira Flores Bridge, Santiago



Stoppers for uplift?

- They were set not for preventing TR offset of bridges but for uplift prevention
- They were too weak



Skewed PC girder bridges recently built without diaphragms and effective side stoppers suffered extensive damage

Hospital Bridge
Route 5


Recent practice



From Web


Pre mid-1990s Chile design
practice

Collapse due to rotation of a skew bridge



Older bridge based
on Pre Mid-1990s
Chile Design Practice
performed well

Abutments and piers
were built perpendicular
to bridge axis (straight
bridge)




No damage of PC
girders and no offset of
bridge





Stable abutments

Jan Pablo II Bridge



Various types of failure of columns and lateral beams



Thank you for long contribution!

Rio Claro Bridge

A 140 years old unreinforced masonry bridge built in 1870







Claro Bridge
survived heavy
duty for long time

Brittle masonry
easy to remove
clay soil




- Arch crown was only 3m thick
- It must be very tuff to survive heavy traffic

Thank you for long contribution!

Bio Bio Bridge

- Built in 1930s
- Recognized to be insufficient for traffic since 1990s based on JICA evaluation



Tubul Bridge Apauco

Insufficient
performance
of foundations



Rupture of Elastomeric Bearing

Las Balenas Bridge
Local Road, Suburbs of
Conseption



A 15 cm tall
60cm by 60cm
elastomeric
bearing ruptures
due to shear at
shear strain of
about 70%

A new bridge constructed based on the existing Chile design survived with only very minor damage

- Side stoppers
- Diaphragms



SUMMARY

- Lack of integrity of a bridge due to absence of diaphragms and effective stopper mechanism in the transverse offset resulted in extensive damage in bridges built after the mid 1990s.
- The above deficiency was particularly intensified in skewed bridges resulted from rotation of a whole bridge.
- In contrast to the bridges built after the mid 1990s with insufficient insight to the seismic effects, the bridges which were built based on the original Chile practice did not suffer extensive damage.

SUMMARY (continued)

- Damage of columns/piers and foundations was not extensive except those in bridges built in the early days. However it is suggested to clarify their strength and deformation capacity if Chile practice moves toward higher connection between decks and substructures for limiting relative displacement.

ACKNOWLEDGEMENTS

Damage investigation of bridges was supported by number of personals. Special appreciation is extended to Ing. Fernandez, M., Ing. Ortega, J.M., Ing. Carracedo, M., Ing. Guzman, M., Ing. Achvrra, S., Ing. Concha, A., Ing. Valdebenito, R. (Ministry of Public Works), Dr. Celebi, M. (USGS), Professor Saragoni, G.R. (Univ. Chile), Professor Alvarado, R.V. (Catholica Univ.), Professor Fishingier, M. (Univ. Lubujana), Professor Omer, A. (Tokai Univ.) and Ing. Furukawa, K. (Interpreter).