Damage of Bridges Resulted from March 11, 2011 East-Japan Earthquake

April 15, 2011

Kazuhiko Kawashima Department of Civil Engineering Tokyo Institute of Technology

Introduction

This slide set shows damage of transportation facility due to the East-Japan earthquake, March 11, 2011. The field damage investigation was conducted on March 29-Arpril 3, 2011 by the author with other 12 members of the Japan Society of Civil Engineers' reconnaissance damage investigation team. The cooperation of the team members is greatly acknowledged. The view shown here is that of the author, and does not necessarily represent the view of Japan Society of Civil Engineers.

JSCE Reconnaissance **lachinohe** Site damage Investigation Kesennuma, Rikuzen-Takada, Ofunato orioka Miyako Kamaishijshinomaki, Furukawa, Wakuya, Tukudate Ofunato W Nosakuzen-Takada esernuma Sendai, Yuriage **Usino**maki atori

Preliminary Report on the Damage of Civil Engineering Structures Resulted from March 11, 2011 East-Japan Earthquake

http://committees.jsce.or.jp/report/node/40

Table of Contents

- 1. Introduction
- 2. Member of the Team and Itinerary
- 3. Geology and Ground Condition
- 4. Earthquake & Earthquake ground Motion
- 5. Tsunami
- 6. Failure of Manmade Land for Housings
- 7. Damage of River Dykes
- 8. Liquefaction at Furukawa City
- 9. Damage of Bridges

After-shock Area Between 12:00, March 11 and 12:00, March 23 by JMA



Preliminary Analysis of the Fault Mechanism by NLED



Direction: 195 degree
Dip: 13 degree
Size: 501kmX210km
Maximum slip: 23m
M_w=8.9



Characteristics of near-source ground motions

K-NET Strong Motion Records







Comparison with 2 typical near-field ground motions during the 1995 Kobe, Japan earthquake JMA Kobe & JR Takatori Station







Local tsunami height is being investigated.
It is reported that tsunami run up 23 m at a site in Ofunato City.

Kesen-numa City From Kesennuma Junior High School







Field damage investigation for bridges was conducted focusing on the following issues:

 Was the ductility capacity method which was enforced in design of road bridges since 1990 effective for mitigating damage?

Was the extensive use of elastomeric bearings since 1995 Kobe earthquake effective for mitigating damage of bearings?
What types of damage occurred to bridges due to tsunami?

Seismic performance of bridges supported by elastomeric bea

Sendai Bridge (Route

Shin-Tenno Bridge (Sar

Bridges supported by elastomeric bearings did not suffer damage

linogawa Bridge, Route 45

Higashi Matsuyama Bridge, Route 45

Existing damage still continue to occur in the existing stee Tenno Bridge Route 45

Pull-out of Anchor Bolts

Main bridge

Pedestrian bridge

Rupture of Elastomeric Bearings Occurred at Two Locations Close Each Other

East Sendai Road, NEXCO-East





Bearings Damaged

Separation of a subber layer and a steel p

The steel plate bent in double in a complex manner



Separation of rubber layers from steel plates did not occur in the past



How large shear strain was induced in the rubber layers?
Was the bearing properly fabricated?

Unretrofitted Shinkansen columns suffered extensive damage





Extensive Damage of Shinkansen Viaduct during 2003 Miyagi-ken-oki



arthquake

Kesen Bridge Route 45 Rikuzen-Takada City



The superstructure was washed away 310 m upstream

Kesen Bridge

Damage of Bearings and Side-Blocks at the Right Abutment

Failed side-bloc

Parapet-wall of the right abutment

Damage of parapet-wall resulted when the deck was washedaway

Ruptured elastomeric bearing.

Damage of Dampers Installed for Seismic Retrofit

Four dampers at the right abutment

Failed elastomeric bearings

Four dampers

Right abutment

Utazu Bridge Route 45 Rikuzen-Takada City



Some cable restrainers were still alive

Installed in 2005 for seismic retrofit

6 本中 №.

会社

Steel stoppers were provided, but they were ineffective for preventing transverse deck movement & uplift by tsubamine





Two 3-span continuous superstructures were washed away upstream

Superstructure





350 m upstream

Another superstructure was washed away 450m upstream at the left side bank

Trace left on the left dyke showing that the bridge was

along

Second bridge

Damaged steel bearings on P2

P3 must be somewhere around here

P2

Support condition of a bridge on A2 abutment

Cable restrainers

Collapsed side block

our campers for

seismic retrofit

Sliding bearing

Shin-Kitakami Bridge Regional Road over Kitakami River

Upstream

Upstream

Two spans were washed away several hundreds meters upstream



Full of Debris on the Deck



Deck floors of a side pedestrian bridge (upstream side) uplifted to rotate by 90 degree from the ginders of the side of the si

They contributed to increasing of water pressure



Jibbers for connection

Abutment seat from where the span fel



Roller bearing which supported the uncollapsed bridge



Two piers and the left side abutment did not suffered damage



Numata Over Bridge Ropute 45 Rikuzen-Takada City

Six longitudinal stoppers were provided. They must be effective to prevent transverse movement of the deck.
Unless the decks were uplifted by tsunami, this failure could not happen.



Embankment was completely washed away, and an abutment was left alone





There were a number of bridges which did not suffer damage by tsunami, but back soils & embankment were washed away Kawahara River Bridge Route 45 Rikuzen-Takada City The two story building hit the bridge, but the bridge survived

Temporal bridge

Embankment which was washed away The building

which hit the

TO THE

Bridge

Embankment was completely washed away

Anchors of cable restrainers

A two story building

Cables embedded in the embankment



Furukawa Bridge (Pedestrian Bridge) Takada-no-matsubara Park Rikuzen-takada City



Nijyu-ichi Hama Bridge Route 45 Kesen-numa City



Many short bridges survived tsunami

A Bridge on Route 45 Shizu-gawa town



Damage of the town around the bridge



Guard Rails were washed away

Minato Bridge 150 m downstream of the bridge in the previous slide Shizu-gawa town



Sho-nin Bridge Route 45 Ofunato City





Failure Bridges due to Scouring

 This failure mode was not observed during the East-Japan earthquake since foundations were deep and well constructed



A possible Failure Mechanism of Bridges due to Tsunami



Most Probable Failure Mechanism of Bridges due to Tsunami



Preliminary Findings

 Bridges which were constructed or were retrofitted based on the ductility design method (enforced since the 1990 JRA Design Specifications) suffered almost no damage. It contributed to the enhancement of the seismic performance of bridges.

•Elastomeric bearings including lead rubber bearings and high damping rubber bearings which were introduced since 1990s mitigated damage of bearings. However several elastomeric bearings ruptured at two locations of East Sendai Expressway. Reason of the damage has to be clarified.

Preliminary Findings (2)

•A number of bridges suffered damage by tsunami. Damage was possibly developed by deck rotation toward upstream side, resulted from uplifting force. If failure of bearings (particularly downstream side bearings) due to uplifting force can be prevented, damage of tsunami may be mitigated.

 It is recommended to install "unseating prevention device for tsunami." Restrainers which are widely used for unseating prevention device for earthquake may be effective if they are set in the vertical direction.

Acknowledgements

Deep appreciation is given to Nishioka, T. (Hanshin Expressway Co.), Akiyama, M. (Waseda Univ.), Takahashi, K. (Kyoto Univ.), Watanabe, G. (Yamaguchi Univ.), Matsuzaki, H. (Tokyo Institute of Technology) and Koga, H. (PWRI) as well as Wakamatsu, K. (Kanto Gakuin Univ.) and other members of JSCE reconnaissance team. Appreciation is extended to Ministry of Land, Infrastructure and Transportation, Nexco-East, JR-East, Tahahashi, H., Sakamoto, S. & Kimata, K. (Shimizu Construction Co.), and Yabe, M. (Chodai Consultants). Support of WFEO Disaster Risk Management Committee is acknowledged.